

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to sections 9 and 10, Township 2 North, Range 7 West, W.M., Tillamook County, Oregon.

ORIGINAL

16" x 10" x 8" basalt stone, now in place marked 1/4, from which a:

30" Hemlock bears S53W 62 lks; now 54" snag, scribe marks 1/4 S exposed.

32" Hemlock bears N76E 29 lks; now 50" snag, scribe marks 1/4 S exposed.

RESTORED CORNER

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S9 S10 1952 2311," 2 1/2" in ground. Placed 1/4 stone on north edge of pipe.

Placed an Oregon State Board of Forestry metal location poster on 50" Hemlock snag BT and marked it: Sec 10 T2N R7W 1/4 Cor 19.4 Ft. S78°30'W.

Dated June 7, 1952.

This corner was restored by Don D. Davis under my direction. Don D. Davis Assistant Forest Engineer



Present and witnessed by Richard A. Morris Richard A. Morris Compassman

Present and witnessed by Robert A. Young Robert A. Young Chairman