

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One-quarter corner common to sections 18 and 19, Township 2 North, Range 7 West, W.M., Tillamook County, Oregon.

ORIGINAL

16" x 9" x 8" basalt stone, now missing; point falls on edge of logging road cut, from which a:

- 8" Hemlock bears N06°W 21 lks.; now missing.
- 18" Hemlock bears S55E 59 lks.; now missing, but found by our department in May 1951, with scribe marks 1/4 S B exposed.

Position of corner point determined from Oregon State Board of Forestry metal location poster placed on 38" burned Hemlock stub N18W 20 feet by our department in May 1951.

WITNESSED CORNER

As point for 1/4 corner falls on edge of logging road cut,

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY WC 1/4 S18 S19 10 Ft. E. 1952 2311," 2 1/2' in ground, 10 feet west of one-quarter corner point. Raised mound of stone around witness corner pipe, from which a:

- 56" Fir snag bears N58°30'W 83.3'; scribed X BT RE 2311.
- 68" Fir stump bears S30E 137.0'; scribed X BT.

Placed an Oregon State Board of Forestry metal location poster on 33" Fir snag on East edge of logging road and marked it: Sec 18 T2N R7W W C 1/4 Cor 33.1 Ft. S88°W.

Dated December 17, 1952.

This corner was restored by Don D. Davis Assistant Forest Engineer  
under my direction.



Present and witnessed by Gerald M. Schwalen, Chainman.