

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to sections 5, 6, 31, and 32, Townships 2 and 3 North, Range 8 West, W.M., Tillamook County, Oregon.

ORIGINAL

16" x 8" x 6" basalt stone, now missing, from which a:

- 36" Fir bears N82E 21 lks.; now 44" snag, scribe marks 3 N R8W S32 exposed. Did not attempt to expose scribe marks BT.
- 30" Hemlock bears S25E 36 lks.; now missing.
- 15" Hemlock bears S22W 51 lks.; now missing.
- 18" Hemlock bears N72W 40 lks.; now missing.

RESTORED CORNER AND WITNESSED CORNER POINT

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T3N R8W S31 S32 S6 S5 T2N 1953 2311," 2 1/2' in ground. Raised mound of stone around corner pipe, from which a:

- 52" Fir snag bears N41°30'W 53.8'; scribed T3N R8W S31 BT.
- 50" Fir snag bears S42°30'W 9.3'; scribed T2N R8W S6 BT RE 2311.
- 36" Fir snag bears S07°30'E 31.0'; scribed T2N R8W S5 BT.

Placed an Oregon State Board of Forestry metal location poster on original BT now 44" Fir snag and marked it: Sec 32 T3N R8W Sec Cor 13.9 Ft. S82°W.

Dated January 7, 1953.

This corner was restored by Don D. Davis Assistant Forest Engineer

under my direction.



Present and witnessed by Robert A. Young, Compassman.

Robert J. Cowan, Chainman.