

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to sections 25, 26, 35, and 36, T2N R8W, W.M., Tillamook County, Oregon.

ORIGINAL

16"x9"x7" basalt stone, now missing, from which a:

- 60" Fir bears N50°30'E 18 lks; now 66" stub 6' high.
- 50" Fir bears S66E 58 lks; now 52" snag S68E, scribe marks T2N R8W S36 exposed.
- 18" Hemlock bears S47W 51 lks; now missing.
- 9" Hemlock bears N75W 26 lks; now missing.

RESTORED CORNER AND WITNESSED CORNER POINT


Set 1½"x36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T2N R8W S26 S25 S35 S36 1952 2311," 2½' in ground. Raised mound of stone around corner pipe, from which a:

- 54" Fir stump bears S34°15'W 72.6'; scribed T2N R8W S35 BT.
- 48" Fir snag bears N66W 63.4'; scribed T2N R8W S26 BT.
- 66" Fir stub 8' high bears N48E 11.4'; scribed T2N R8W S25 BT RE2311.

Placed an Oregon State Board of Forestry metal location poster on original BT now 66" Fir stub 8' high and marked it: Sec 25 T2N R8W Sec Cor 11.4 Ft. S49W.

Dated December 11, 1952

This corner was restored by Don D. Davis, under my direction, Don D. Davis Assistant Forest Engineer



Present and witnessed by Gerald M. Schwalen, Chainman.

SEE LATER RESTORATION OF CORRECTED POSITION RECORDED IN BOOK 7, PAGE 329  
 AGG; C.S.  
 10-12-00