

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Closing corner common to sections 1, and 6, Township 1 South, Ranges 6 & 7 West, W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

- 12" Hemlock bears S63°30'W 53 lks.; now 12" stub.
- 16" Hemlock bears S03°30'E 55 lks.; now 18" down stub scribe marks CC T1S R exposed.
- 6" Hemlock bears N49°W 6 lks.; now 6" stub 18' high, parts of scribe marks BT exposed.

RESTORED


Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T1N R7W S36 S1 S6 R7W R6W T1S CC 1953 2311," 2½' in ground. Raised mound of stone around corner pipe, from which a:

- 46" Hemlock bears S41°45'E 47.5Ft.; scribed T1S R6W S6 CC BT RE 2311.
- 29" Fir bears S57°W 37.8 Ft.; scribed T1S R7W S1 CC BT.

Placed an Oregon State Board of Forestry metal location poster on 36" Hemlock, scribe marks BM 2166.38 exposed, and marked it: Sec 36 T1N R7W CC 1 6 Cor 4.2 Ft. S12E.

Dated January 14, 1953.

This corner was restored by Don D. Davis  
Don D. Davis Assistant Forest Engineer  
under my direction.



Present and witnessed by Robert J. Cowan.