

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Standard corner common to sections 31, and 36, Township 1 North, Ranges 6 & 7 West, W.M., Tillamook County, Oregon.

ORIGINAL

Basalt stone 18" x 9" x 8", now missing, from which a:

- 30" Fir bears N20W 21 lks.; now 4 1/2" Fir stump.
- 12" Hemlock bears N75E 42 lks.; now 2 1/2" snag, scribe marks 6W 1N exposed.
- 18" Hemlock bears S55E 45 lks.; now 36" snag, face grown over.
- 30" Fir bears S40W 49 lks.; now 35" snag, exposed scribe marks BT.

RESTORED

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY SC TLN R7W R6W S36 S31 1953 2311," 2 1/2' in ground. Raised mound of stone around corner pipe, from which a:

- 4 1/2" Fir stump bears N30E 32.4 ft.; scribed TLN R6W S31 SC BT RE 2311.
- 4 1/2" Fir stump bears N20W 13.6 ft.; scribed TLN R7W S36 BT.


Placed an Oregon State Board of Forestry metal location poster on 4 1/2" Fir stump BT and marked it: Sec 31 TLN R6W Standard cor 32.4 Ft. S30°W.

Dated January 14, 1953.

This corner was restored by

*Don D. Davis*  
Don D. Davis Assistant Forest Engineer

under my direction.



Present and witnessed by Robert J. Cowan.