

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One-quarter corner common to section 36, Township 1 North,  
Range 7 West, W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

- 20" Fir bears N81°W 38 lks.; now 26", scribe marks 1/4 S on down snag, broken off at roots.
- 18" Fir bears N44°E 43 lks.; now 32" snag, old face burnt out.

RESTORED


Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S36 1953 2311," 20 inches in ground. Raised mound of stone around corner pipe, from which a:

- 29" Fir snag bears N12°30'W 29.6'; scribed 1/4 S36 BT RE 2311.
- 32" Fir snag bears S26°W 19.0'; scribed 1/4 S36 BT.

Placed an Oregon State Board of Forestry metal location poster on 29" Fir snag BT and marked it: Sec 36 T1N R7W E 1/4 Cor 29.6 Ft. S12°30'E.

Dated January 15, 1953.

This corner was restored by Don D. Davis  
Don D. Davis Assistant Forest Engineer  
under my direction.



Present and witnessed by Robert J. Cowan.