

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 2, 3, 10 and 11 T1S R8W,  
W.M., Tillamook County, Oregon.

ORIGINAL

Stone, 18"x10"x10", now missing, from which a:

- 10" alder bears N22W 107 lks.; missing--slide area.
- 10" Alder bears N42E 131 lks.; missing--slide area.
- 6" Spruce bears S42E 62 lks.; missing
- 8" Alder bears S53W 36 lks.; now 20" x 10 ft high stub,  
chopped out cast of scribes.

RESTORATION by W. E. Anderson Apr. 7, 1932.

- 14" Spruce bears S40E 42 ft.; now 16 Ft stub, CS BT scribe.
- 12" Spruce bears S76W 30 ft.; missing--slide area.

RESTORED

Set 1 1/2"x40" galvanized iron pipe with 3" bronze cap marked  
"Oregon State Board of Forestry T1S R8W S2 S3 S10 S11  
1953 2311", 36 inches in ground, in mound of rock, and  
from which a:


- 24" Cedar snag bears N65E 96 ft.; scribed T1S R8W  
S2 BT.
- 18" Alder bears N51 1/2 W 51.5 ft.; scribed T1S R8W  
S3 BT.
- 8" Alder bears S31E 57 ft.; scribed T1S R8W S11 BT  
in bark.
- 78" Fir stump bears S29°30'W 176 ft.; scribed T1S R8W  
S10 RE 2311 BT.

Oregon State Board of Forestry metal location poster on 18"  
Alder BT.

Also poster on SW side of 78" Fir stump BT.

Dated March 11, 1953

Restored by Arnold E. Gibson under my direction.  
Arnold E. Gibson, Assis Engineer



Present and witnessed by Robert A. Cowan