

CHAINS

REESTABLISHED CORNER FOR OREGON STATE BOARD OF FORESTRY
(See official plat)

One quarter corner common to Sections 10 and 15, T. 1N., R. 7W.,
W.M., Tillamook County, Oregon

ORIGINAL

(No evidence was found of the original corner)

REESTABLISHED

Var. $21\frac{1}{2}^{\circ}$

Set $1\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked
"OREGON STATE BOARD OF FORESTRY 1/4 S10 S15 1956 RS359,"
34 inches in ground, in mound of stone, and from which a:

68" Fir stump bears $N19^{\circ}E$. 99.5 ft.; scribed 1/4 S10BT
RS359 (located on 20 ft. x 150 ft. flat E & W)


6" Alder bears $N42\frac{1}{2}^{\circ}E$. 50.8 ft.; scribed 1/4 S10BT
(in bark)

Oregon State Board of Forestry metal location poster on 68"
Fir stump BT.


Set 4 x 3 x 60" white painted cedar post 1.5 ft. SE of pipe

Dated March 23, 1956

Reestablished by _____



Arnold G. Gibson



Present and witnessed by Richard Morris
Robert Sturm
Lloyd Geraths