

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One Quarter corner common to Sections 5 and 8, T. 3S., R. 7W., W.M., Tillamook County, Oregon

ORIGINAL

Post (missing) from which a:

20" Hemlock bears N. $89\frac{1}{2}^{\circ}$ E. 42 lks.; now just roots remaining in place.

30" Hemlock bears S. $37\frac{1}{2}^{\circ}$ W. 60 lks.; now 36" snag, edges of charred upper and lower face remaining, with scribes visible on lower.

RESTORED

Var. $21\frac{1}{2}^{\circ}$ E.

Set $1\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S5 S8 1957 RS359," 35 inches in ground and from which a:



19" Cedar snag bears N. $88\frac{1}{2}^{\circ}$ E. 50.8 ft.; scribed 1/4 S5 BT.

66" Fir stump bears S. 74° E. 48.8 ft.; scribed 1/4 S8 BT RS359.

Oregon State Board of Forestry metal location poster on 19" Cedar snag BT. Set 4" x 4" x 60" white painted Cedar post 1.5' N.W. of pipe.

Dated April 24, 1957

Restored by Richard Morris under my direction.
Richard Morris, Transitman



Present and witnessed by Robert Sturm