

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One Quarter corner common to Sections 8 and 17, T. 3S., R. 7W.,
W.M., Tillamook County, Oregon.

ORIGINAL

Post (missing) from which a:

7" Fir bears S. $76\frac{1}{2}^{\circ}$ E. 19 lks.; now 15" snag, Scribes
4S visible, rest unexposed.

8" Fir bears N. $18\frac{1}{2}^{\circ}$ W. 22 lks.; now missing.

RESTORED

Var. $21\frac{1}{2}^{\circ}$ E.

Set $1\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked
"OREGON STATE BOARD OF FORESTRY 1/4 S8 S17 1957 RS359,"
34 inches in ground, and from which a:

22" Fir bears S. 84° E. 17.8 ft.; scribed 1/4 S17 BT.



23" Fir bears N. 18° W. 33.3 ft.; scribed 1/4 S8 BT
RS359.

Oregon State Board of Forestry metal location poster on 22"
Fir BT.

Set 3" x 3" x 60" white painted Cedar post 1.5 ft. NW of
pipe.

Dated April 24, 1957

Restored by Richard A. Morris under my direction
Richard A. Morris, Transitman



Present and witnessed by Robert Sturm
Everett Hunt