

Rewitnessed Corners. T5&6S R10W. Mervin Whitmore U.S. Forest Service.

~~CHAINS~~
Sec. Cor.
35 | 36

Set post (Original post gone)
A 24" alder bears N15°W 32 lks. scribing visible after being chopped open. (Old BT)
A 14" dead alder stub bears S78°W 62 lks. dist. (Old BT)
A 30" fir bears S40°E 26 lks. dist. Did not open. (Old BT)
A 42" fir bears N77°E. 30.5 feet dist. mkd. T5S R10W. S36BT (New BT)

In the presence of Willis Horner. February 28, 1957.

Rewitnessed Corner T6S R10W. Mervin Whitmore U.S. Forest Service.

~~CHAINS~~
Sec. Cor.
6 | 5
7 | 8

Iron pipe 24" high.
24" hemlock S40°E 4lks. (Old BT)
10" dead hemlock stub, S32°W. 11 lks. (Old BT)
16" spruce N28½°E. 83½ feet. slope dist. mkd. T6S R10W S5BT. ~~S6BT~~. (New BT)
25" spruce N5°W. 113 feet slope dist. mkd. T6S R10W S6BT. (New BT)

In the presence of Wayne Bronson and Rene Elisar. Dec. 18, 1956.

BOOK 2

The quarter section corner is so described:

Erected 4" x 4" x 72" hemlock post, 24" in ground
Yellow aluminum tag on post reads "¼ sec. cor. 30/51
Transit & tape J.L. Carlich # 287, J. Madison 8/28/56"

Made bearing trees:

- a) 18" hemlock bears S. 85°E., 15.0 feet
scribed "¼ S. B.T. #287"
- b) 24" hemlock bears N. 82°E., 42.4 feet
scribed "¼ S. B.T. # 287"

On both bearing trees placed aluminum tag reading
"¼ S. B.T. 30/51, Transit & tape"

This corner is beside an uprooted windfall 50 feet more or less
North of a brook which flows WSW.

(¼ Corner 30/51 T. 2 S., R. 10 W., W.M.)

BOOK 2

BOOK 2

373

373