

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Sections 2 and 11,  
T. 2N, R. 9W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (missing) from which a:

12" Hemlock bears N49°E 77 lks.; now 26" stub,  
10' high, scribes S BT remaining.

15" Hemlock bears S43°E 41 lks.; now missing, just roots  
remaining in place.

RESTORED

Var. 21½°E

Set 1½" x 36" galvanized iron pipe with 3" bronze cap  
marked "OREGON STATE BOARD OF FORESTRY ¼ S2 S11 1957  
RS 401," 35 inches in ground, and from which a:

76" Fir stump bears N36°W 51.2 ft.; scribed ¼ S2 BT.

50" Fir stump bears S82°W 48.6 ft.; scribed ¼ S11 BT RS 401.

Oregon State Board of Forestry metal location poster on  
50" Fir stump BT.


Set 4"x4"x60" white Cedar post 1.0' NE of pipe.

Dated June 17, 1957.

Restored by



*Richard A. Morris*



Present and witnessed by Warren Peterson