

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 10, 11, 14 and 15 T. 1N., R. 9W., W.M., Tillamook County, Oregon.

ORIGINAL

Stone, 17" x 10" x 9" (now missing) from which a:

13" Hemlock bears N.37°W. 27 lks.; now 20" uproot, roots and root hole in place, scribes T 1N. R 9 visible, rest burnt out.

12" Hemlock bears N.26°E. 30 lks.; now missing.

10" Hemlock bears S.67°E. 11 lks.; now missing.

9" Spruce bears S.54°W. 28 lks.; now 12" stub 10' high, edges of burnt out face visible.

RESTORED

Var. 21-1/2° E.

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T1N R9W S10 S11 S15 S14 1957 RS401," 26 inches in ground, in mound of stone, and from which a:

16" Fir snag bears N.48°W. 52.0 ft.; scribed T1N R9W S10 BT.

26" Fir snag bears N.4°E. 24.2 ft.; scribed T1N R9W S11 BT.

24" Fir snag bears S.53°E. 37.0 ft.; scribed T1N R9W S14 BT RS401

25" Fir snag bears S.16°W. 22.8 ft.; scribed T1N R9W S15 BT.


Oregon State Board of Forestry metal location poster on 24" Fir snag BT. Set 4" x 4" x 60" white painted cedar post 1.0' NW.

Dated June 4, 1957

Restored by



*Richard A. Morris*



Present and witnessed by Robert Sturm,