

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One Quarter corner common to Sections 3 and 10,
T1N, R10W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (now missing) from which a:

- 4" Elder bears S3W 9 lks.; now missing.
- 10" Hemlock bears N76W 11 lks.; now 16", scribe S exposed, rest of face unexposed.

RESTORED

Var. 21 $\frac{1}{2}$ E


Set 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S3 S10 1960 RS401", 34 inches in ground, and from which a:

- 20" Hemlock bears S48 $\frac{1}{4}$ E 28.4 ft.; scribed 1/4 S10 BT RS401.
- 35" Hemlock bears N37 $\frac{1}{2}$ W 28.9 ft.; scribed 1/4 S3 BT.

Oregon State Board of Forestry metal location poster on 20" Hemlock BT.
Set 3" x 4" x 52" white painted Cedar post 1.0' S.E. of pipe.

Dated December 2, 1960

Restored by Harold J. Russell under my direction.
Harold Russell, Transitman



Richard A. Morris
MAY 10, 1957
Richard A. Morris
401

Present and witnessed by G. E. Nylund
J. Sehorn

[Handwritten signature]