

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 19, 24, 25 and 30, T2N, R8 & 9W, W.M., Tillamook County, Oregon.

ORIGINAL

Stone 22" x 12" x 10" (now in place with 5 notches on N. edge, S. edge broken off) from which a:

- 26" Fir bears N31W 39 lks.; now 24" badly burnt snag, face and scribes all burnt away.
- 8" Hemlock bears N34E 68 lks.; now missing.
- 5" Hemlock bears S61E 43 lks.; now missing.
- 21" Fir bears S 42W 45 lks.; now 20" badly burnt stub.

RESTORED

Var. 21 1/2 E

Erected mound of stone around original corner stone, from which a:


- 40" Fir snag bears N4E 50.4 ft.; scribed T2N R8W S19 BT RS401.
- 31" Fir snag bears N76W 38.3 ft.; scribed T2N R9W S24 BT.
- 44" Fir snag bears S25E 55.0 ft.; scribed T2N R8W S30 BT.
- 38" Fir stub 8' high bears S26W 5.5 ft.; scribed T2N R9W S25 BT.

Oregon State Board of Forestry metal location poster on 36" Fir snag on top of main ridge top S5E 47.6'.


Set 4" x 4" x 52" white painted Cedar post 1.0' S.W. of corner stone.

Dated October 17, 1960

Restored by



Richard A. Morris



Present and witnessed by Harold Russell
George Nylund

297