

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 7, 12, 13 and 18, T3S, R8 & 9W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (found possible original post with 3/4" iron pipe alongside) from which a:

- 60" Fir bears S40E 50 lks.; now 41" snag, scribes 8W 3S visible.
- 60" Fir bears N25E 66 lks.; now 60" stub 15' high, no scribes visible.
- 50" Fir bears S70W 5 lks.; now 43" snag, scribes T3S R9W S13 BT visible.

RESTORATION July 16, 1896

- 5" Fir bears N28W 21 lks.; now 18" scribes S12 visible, rest unexposed.
- 6" Fir bears S55E 5 lks.; now missing.

RESTORED

Var. 21 1/2 E


Set 4" x 4" x 60" white painted Cedar post 1.0' N.W. of above pipe from which a:

- 14" Fir bears N29E 11.7 ft.; scribed T3S R8W S7 BT RS401.
- 18" Fir bears S59E 18.8 ft.; scribed T3S R8W S18 BT.
- 21" Fir bears N70W 12.8 ft.; scribed T3S R9W S12 BT.
- 20" Fir bears S14W 44.1 ft.; scribed T3S R9W S13 BT.

Oregon State Board of Forestry metal location poster on 14" Fir BT.

Dated November 17, 1960

Restored by Robert Cop under my direction.  
Robert Cop, Forestry Aide



Present and witnessed by G. Nylund

