

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 11, 12, 13 and 14, T3S, R10W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (missing, found 1 1/4" x 54" iron pipe over a 3/4" iron pipe 18" out of ground, in place) from which a:

- 14" Hemlock bears N2W 14 lks.; now 18" snag, portions of scribe visible.
- 10" Hemlock bears N85E 11 lks.; now missing, position falls on edge of cat road.
- 18" Hemlock bears S40W 45 lks.; now 30" stub 8" high, scribes BT visible.
- 20" Hem bears S54E 20 lks.; now missing, position falls on edge of cat road.

RESTORED

Var. 21 1/2 E


Set 4" x 4" x 52" white painted Cedar post 1.0' west of above pipes from which a:

- 8" Hemlock bears N26 1/2 W 4.3 ft.; scribed T3S R10W S11 BT.
- 9" Hemlock bears S69W 10.4 ft.; scribed T3S R10W S14 BT.
- 8" Hemlock bears N36E 43.8 ft.; scribed T3S R10W S12 BT RS401.
- 6" Hemlock bears S5 1/2 E 21.9 ft.; scribed T3S R10W S13 BT.

Oregon State Board of Forestry metal location poster on 8" Hemlock N26 1/2 W 4.3'

Dated December 2, 1960

Restored by



Present and witnessed by H. Russell
R. Cop
G. Nylund