

CHAINS

RE-ESTABLISHED CORNERS FOR OREGON STATE BOARD OF FORESTRY  
(See official plat)

One Quarter corner common to Sections 34 and 3, T1 and  
2N, R10W, W.M., Tillamook County, Oregon.

No evidence of original corner found.

RE-ESTABLISHED

Var. 21 1/2 E

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE  
BOARD OF FORESTRY 1/4 S34 S3 1961 RS401", 34 inches in ground, and from  
which a:

14" Hemlock bears S16 1/2 W 32.8 ft.; scribed 1/4 S3 BT.

21" Hemlock bears N11 E 5.8 ft.; scribed 1/4 S34 BT RS401.

Set 4" x 4" x 52" white painted Cedar post 1.0 ft. S.W. of corner pipe.  
Oregon State Board of Forestry metal location poster on 21" Hemlock BT.

\*\*\*\*\*

One Quarter corner common to Sections 1 and 6, T1N, R9 and  
10W, W.M., Tillamook County, Oregon.

No evidence of original corner found.

RE-ESTABLISHED at a point on the true range line and

Var. 21 1/2 E

S0°28'39"W 66.0' from summit of ridge set 1 1/2" x 36"  
galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF  
FORESTRY 1/4 S1 S6 1961 RS401", 18 inches in ground, between roots of  
48" Fir uproot, and from which a:

10' x 10' rock outcrop bears N24 E 31.1 ft.; scribed XBO.

7" Hemlock bears N70 W 9.1 ft.; scribed 1/4 S1 BT RS401.


Set 4" x 4" x 52" white painted Cedar post 1.5 ft. N.W. of corner pipe.  
Oregon State Board of Forestry metal location poster on 7" Hemlock BT.

Dated February 27, 1961

Re-established by



*Richard A. Morris*



Present and witnessed by H. Russell  
R. Cop  
E. Nylund

468