

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 1, 6, 7 and 12,
T3S, R9 & 10W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (missing) from which a:

- 18" Hemlock bears N26E 7 lks.; now 2' high rotten stub, face and scribes rotted away.
- 18" Hemlock bears N89W 40 lks.; now possible roots remaining in place.
- 20" Hemlock bears S24W 45 lks.; now missing.
- 5" Hemlock bears S16E 77 lks.; now missing.

RESTORATION December 20, 1923 by W. E. Anderson, County Surveyor.

Post (now 24" long, in place, scribes S1 S6 S7 S12 CS visible) from which a:

- 8" Spruce bears S 6° 22'W 38.6 ft.; now 23", face completely grown over.
- 6" Spruce bears N76° 17'W 43.1 ft.; now 9" snag, scribes CS visible, rest unexposed.
- 10" Hemlock bears N24°57'W 92.0 ft.; now 30", scribes BT R9-10 CS visible, rest of face unexposed.
- 8" Hemlock bears N57°07'E 84.2 ft.; now 30", face completely grown over.

RESTORED

Var. 21½E

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T3S R10W R9W S1 S6 S12 S7 1961 RS401", 34 inches in ground, and from which a:

- 18" Spruce bears S6E 35.3 ft.; scribed T3S R9W S7 BT RS401.
- Above 23" Spruce bearing S6°22'W 38.6 ft.; scribed BT.
- Above 30" Hemlock bearing N24°57'W 92.0 ft.; scribed BT.
- Above 30" Hemlock bearing N57°07'E 84.2 ft.; scribed BT.

Oregon State Board of Forestry metal location poster on 15" Hemlock S60W 21.6'.


Set 4" x 4" x 52" white painted Cedar post 1.0' N.W. of pipe.

Dated February 14, 1960

Restored by Harold Russell under my direction.
Harold Russell, Eng. Tech. I



Richard A. Morris



Present and witnessed by G. E. Nylund