

CHAINS

RESTORED CORNER FOR STATE OF OREGON-DEPARTMENT OF FORESTRY

One quarter corner common to Sections 15 and 22, T1N, R9W, W.M., Tillamook County, Oregon.

ORIGINAL

Stone 24" x 18" x 7" (missing) from which a:

20" Fir bears N33W 48 lks.; now 24" rotten stub 3' high, axe work at bottom of face remaining, rest of face and acsribes rotted away.

5" Hem. bears S5½W 35 lks.; now 8" rotten stub 2' high, scribes and face rotted away.

Original line blazes East and West of corner.

RESTORED

Var. 21½ E.

Marked X in rock outcropping from which a:

35" Fir snag bears S33E 55.1 ft.; scribed 1/4 S22 BT RS401.

Rock outcrop bears N24½E 1.8 ft.; marked B0.

Set 4" x 4" x 60" white painted Cedar post 2.5 ft. SW of corner point.

Oregon State Forestry Department metal location poster on 35" Fir snag BT.

Dated June 4, 1964.

Restored by Harold J. Russell under my direction.
Harold J. Russell, Transitman

Present and witnessed by A. Duncan
C. Curl



Richard A. Morris

