

CHAINS

RESTORED CORNER FOR STATE OF OREGON-DEPARTMENT OF FORESTRY

One quarter corner common to Sections 4 and 9, T.2N,
R.9W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (now missing) from which a:

30" Cedar bears N29°E 27 lks.; now 72" stump, face burnt out, axe marks
remaining on backcast.

14" Hem. Bears S12°W 34 lks.; now missing.

REFERENCED by Hammond Engineers

Bench Mark on 30" Hem. bears East 20.0 ft.; now 30" stump. Part of
cruiser mark remaining.

RESTORED

Var. 21½E

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE
BOARD OF FORESTRY 1/4 S4 S9 1963 RS 605", 32 inches in ground and from
which a:


4" Hem. bears East 4.2 ft.; scribed 1/4 S9 BT RS 605.

5" Hem. bears N35½°E 19.0 ft.; scribed 1/4 S4 BT.

Set 4" x 4" x 60" white painted Cedar post 1.0 ft. NE of corner pipe.
Oregon State Forestry Department metal location poster on 5" Hemlock BT.

Dated October 10, 1963

Restored by



Present and witnessed by A. Duncan
C. Curl
L. Hayes