

MORRIS ENGINEERING
1125 Brockwood
McMinnville, Oregon
Phone 472-6706

April 11, 1965


County Surveyors Office
Tillamook County Court House
Tillamook, Oregon

Gentlemen:


Regarding restoration of Section corner common to Sections 32, 33, 5 and 4 of Township 3 South, Range 7 West and Township 4 South, Range 7 West of the Willamette Meridian.

FOUND: Original stone being South 1° East, 584.9 feet from a 4 foot burnt snag as recorded in the original survey notes as a line tree, set 1 inch by 30 inch iron pipe protruding 10 inches from the surface of the ground on South side of stone, from which I marked the following: 22 inch fir, North 30° West marked SC SE 32 BT, a distance of 31.6 feet, also marked a 19 inch fir, South 55° East marked SC NW 4BT a distance of 18.0 feet.

Restoration completed April 4, 1965, compass declination $20^{\circ}45'$ East.



R. M. Morris



576 A

BERT W. UDELL

RT. 3, BOX 8

ALPINE 8-6643

LEBANON, OREGON

September 1, 1964

Tillamook County Surveyor
Court House
Tillamook, Oregon

Dear Sir:

Enclosed herewith is my tracing of a survey I made of Section 22, Township 3 South, Range 8 West of Willamette Meridian in Tillamook County. Enclosed also are notes for each corner set as per U.S.F.S. form R 6-5680-182. I am enclosing self addressed Post cards on which I would appreciate your acknowledgement of the receipt of this survey and the CS number it is recorded under and dropping in the mail to Larry Gossett U.S.F.S. at Hebo and to myself.

All the notes on this survey are on file at the Hebo Ranger Station, Hebo, Oregon.

Sincerely yours,

Bert W. Udell

Bert W. Udell, R.P.E.

CC Larry Gossett, Hebo Ranger Station, Hebo, Oregon.

SEE MAP
A-1177

CHAINS

RESTORED CORNER FOR STATE OF OREGON-DEPARTMENT OF FORESTRY

One quarter corner common to Sections 5 and 8, T3N, R9W, W.M., Tillamook County, Oregon.

ORIGINAL

Stone 14" x 10" x 8" (now missing) from which a:

- 12" Hem. bears N45°W 48 lks.; now 24" Hemlock uproot, scribes 1/ S visible.
- 30" Cedar bears South 54 lks.; now 52" Cedar stump bears South 46.2 ft, no evidence of scribes.
- 20 lk. creek bears East 230 lks.; now in place.

RESTORED

Var. 21½E

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY ¼ S 5 S 8 1964 RS 401", in mound of rock, and from which a:

- 32" Hem. bears S56½°E 71.4 ft.; scribed ¼ S 8 BT RS 401.
- 16" Spruce bears N66°W 14.7 ft.; scribed ¼ S 5 BT.
- 10 ft. creek course N52°W, bears North 16.0 ft.

Set 4" x 4" x 6" white painted Cedar post 1.0 ft. SE of corner pipe. Oregon State Forestry Department metal location poster on 24" Spruce N71°W 9.0 ft.

Dated February 2, 1965

Restored by Allan E. Duncan under my direction.
Allan E. Duncan, Engr. Tech.

Present and witnessed by C. Curl
L. Thompson

