

CHAINS

RESTORED CORNER FOR STATE OF OREGON-DEPARTMENT OF FORESTRY

One - Quarter corner common to Sections 25 and 36, T3S, R10W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (now missing) from which a:

- 40" dead Fir bears N70°E 103 lks.; now 53" snag 40' high, scribes $\frac{1}{4}$ S $\frac{1}{4}$ visible.
- 35" dead stub bears S4°W 35 lks.; now badly rotted mound, roots in place.

RESTORED

Var. 21 $\frac{1}{2}$ °E

Set 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY $\frac{1}{4}$ S25 S36 1965 RS 401", 31 inches in ground, and from which a:

- 15" Hem. bears N76°E 34.3 ft.; scribed $\frac{1}{4}$ S25 BT RS401.
- 12" Alder bears S44 $\frac{1}{2}$ °E 40.6 ft.; bark scribed $\frac{1}{4}$ S36 BT.

Set 4" x 4" x 60" white painted Cedar post 1.0 ft. SE of corner pipe. Oregon State Forestry Department metal location poster 15" Hemlock BT.

Dated June 10, 1965

Restored by Harold J. Russell under my direction.
Harold J. Russell, Transitman

Present and witnessed by A. Duncan

