

CHAINS

RESTORED CORNER FOR STATE OF OREGON-DEPARTMENT OF FORESTRY

Section corner common to Sections 11, 12, 13 and 14,  
T3N, R9W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (now missing) from which a:

- 36" Hemlock bears N7½°E 48 lks.; now missing.
- 40" Cedar bears S22°E 46 lks.; now 40" snag, face and scribes burnt away.
- 28" Cedar bears S74°W 90 lks.; now 28" uproot, face and scribes burnt away, roots in place.
- 38" Cedar bears N86°W 57 lks.; now 51" uproot, roots in place, portion of scribe visible on backcast, portions of backcast remaining around burnt and rotted face.

Creek to North and West now in place.

RESTORED

Var. 21½°E

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T3N R9W S11 S12 S13 S14 1965 RS401", 31 inches in ground, in mound of rock, and from which a:

- 10" Fir bears S76°W 16.7 ft.; scribed T3N R9W S14 BT.
- 17" Fir bears N18½°E 30.2 ft.; scribed T3N R9W S12 BT.
- 12" Fir bears S36¼°E 24.5 ft.; scribed T3N R9W S13 BT RS401.
- 11" Fir bears N17 ¾°W 111.3 ft.; scribed T3N R9W S11 BT.

Set 4" x 4" x 60" white painted Cedar post 1.0 ft. SE of corner pipe. Oregon State Forestry Department metal location poster on 17" Fir BT.

Dated June 8, 1965

Restored by Harold J. Russell under my direction.  
Harold J. Russell, Transitman

Present and witnessed by A. Duncan  
C. Curl



*Richard A. Morris*  
MAY 10, 1957  
Richard A. Morris  
401