

CHAINS

T3S R8W

EVALUATION AND RESTORATION OF LAND SECTION CORNERS

1/4 Corner common to Secs. 29-32 W.M., Tillamook County, Oregon

Original monument: Post

Original witnesses:

- 12" fir, S.75° 15' W., 63 lks, mkd 1/2 S BT.
- 5" fir, N.74° 15' E., 46 lks, mkd 1/2 S BT.

Post gone

Found 54" fir, S.75° 15' W., 41.6 ft. with healed witness face. The N.E. BT is entirely gone.

Found a 38" snag, N.34° E., 159 ft. mkd 1/2 S of which there is no record in the orig. notes. The mks appear to have been made by a pocket knife perhaps 50 or 60 years ago.

I set a 3" x 3" post 24" above ground.

I mark New BT:

16" fir, N.7° E., 19 ft. mkd. 1/2 S 29 BT.

By Leonard Whitmore, Tillamook County Dep. Surveyor. 3-6-65

Witnessed by: M. Whitmore
D. Whitmore

*see BT 3
page 18*

*not acceptable until
field check can be made
12/1/66 J. H. [unclear]*

Book 3