

CHAINS

T5S R10W

EVALUATION AND RESTORATION OF LAND SECTION CORNERS

1/4 Corner common to Secs 26-27 W.M., Tillamook County, Oregon

Original monument: Post

Original witnesses:

10" spruce N.70°E., 30 lks mkd 1/2S BT.

Post Gone

Found 41" spruce, N.70°E., 30 lks with visible mks 1/2S26.

The corner point is 5 ft. east of a creek running north.

I set 3" x 3" post 36" above ground marked 1/2S on East side.

No witness trees in reach in Section 27.

By Leonard Whitmore, Tillamook County Dep. Surveyor, 2-20-65

Witnessed by: Daryl Whitmore
Ananias Gonzales, Choconta, Columbia, S. A.