

Dependent Resurvey of a Portion of the W. Edy. of T. 1 E., R. 6 N.

Chains

A hemlock snag, 45 ins. diam., bears S. $64\frac{1}{2}^{\circ}$ W., 68 lks. dist., with no marks remaining.

A hemlock, 40 ins. diam., bears N. 44° E., 34 lks. dist., with scribe marks S24 visible on partially opened blaze. (Record bearing, N. 53° W.)

At the corner point

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.

T 1 S	
S 24	R 3 W
S 25	S 19
R 9 W	
1958	

from which new bearing tree:

A hemlock, 10 ins. diam., bears S. $63\frac{1}{2}^{\circ}$ W., 124 lks. dist., mkd. T1S R9W S25 BT.

N. $0^{\circ} 57'$ W., beginning new measurement.

Descend 55 ft. over N. slope.

1.22 Branch, 3 lks. wide, course N. 70° W.; ascend 116 ft. over SW. slope.

5.75 Spur ridge, bears NW. and SE.; descend 140 ft. over NE. slope.

9.04 Point for the witness corner to the $\frac{1}{4}$ sec. cor. of Section 19 only.

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.

WC	
↑	T 1 S
	$\frac{1}{4}$ S 19
	R 3 W
1958	

from which

A spruce, 37 ins. diam., bears N. 76° E., 103 lks. dist., mkd. WC $\frac{1}{4}$ S19 BT.

A hemlock, 27 ins. diam., bears S. 75° E., 132 lks. dist., mkd. WC $\frac{1}{4}$ S19 BT.

9.18 True point for the $\frac{1}{4}$ sec. cor. of Section 19 only, at proportionate distance, falls on rock face at head of ravine, course N. 10° E.; there is no remaining evidence of the original corner.

Descend 353 ft. over steep, rocky NE. slope, changing to N. slope.

16.07 Ravine, drains N. 30° E.; descend 92 ft. along steep E. slope.

22.46 Spur, slopes N. from S. 20° W.; descend 155 ft. over N. slope, on spur.

27.65 Point for the N $1/16$ sec. cor. of Section 19 only.

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.

BOOK 3

112