

**Dependent Resurvey of a Portion of the W. Bdy. of T. 1 S., R. 8 W.**

Chains

A hemlock, 42 ins. diam., bears S. 59° W., 13 lks. dist., with scribe marks  $\frac{1}{2}$  8 visible on partially opened blaze.

and trees marked by the Oregon State Board of Forestry in 1955:

A spruce, 25 ins. diam., bears N. 89° E., 29 lks. dist., mkd.  $\frac{1}{2}$  87 BT RE2311 on partially healed blaze.

A spruce, 21 ins. diam., bears N. 51½° W., 55 lks. dist., mkd.  $\frac{1}{2}$  87 BT on partially healed blaze.

Add marks BLM 1958 to bronze cap.

A basalt stone, not of record, 18 x 14 x 7 ins., is loosely set 4 ins. in the ground, alongside the iron post, with  $\frac{1}{2}$  chiseled on W. face.

N. 1° 38' E., beginning new measurement.

Descend 756 ft. over NW. slope.

19.30 Branch, 4 lks. wide, course N. 80° W.; ascend 61 ft. over SW. slope.

24.30 Spur, slopes W.; descend 346 ft. over NW. slope.

33.20 Creek, 5 lks. wide, course W.; a waterfall, 50 ft. high, bears East, about 1 ch. distance; ascend 200 ft. over steep S. slope.

36.43 The corner of Sections 6 and 7 only, determined at record bearing and distance from the remaining original bearing tree, recorded and monumented by the Oregon State Board of Forestry with an iron post, 1½ ins. diam., protruding 2 ins. above ground, firmly set, with 3 in. bronze cap mkd.

**Oregon State Board of Forestry**

T 1 S  
R 9 W | R 8 W  
8 12 | 8 6  
      | 8 7  
1955  
RE 2311

from which the remaining original bearing tree:

A burned cedar snag, 80 ins. diam., bears N. 51° E., 14 lks. dist., with illegible scribe marks visible on burned face.

and trees marked by the Oregon State Board of Forestry in 1955:

A hemlock, 10 ins. diam., bears N. 11° E., 27 lks. dist., with scribe marks T1S R8W 36 BT visible on partially healed blaze.

A fir, 18 ins. diam., bears S. 67° E., 8½ lks. dist., with scribe marks T1S R8W 37 BT RE2311 visible on partially healed blaze.

Add marks BLM 1959 to bronze cap.

Land, mountainous.

Soil, rocky clay with numerous rock outcroppings.

Timber, spruce, hemlock, fir, cedar, and alder; undergrowth, salmonberry, devil's-club, huckleberry, and reproduction.

N. 1°53' E., along the W. bdy. of Section 6.

Ascend 11 ft. over S. slope, through heavy timber and dense undergrowth.

BOOK 8

118