

Subdivision survey of Section 21, T5S, R10W, W. M., Tillamook
County, Oregon

A portion of this survey was previously subdivided by John Carlich from 1956 to 1958. Corners established by Carlich, if adjacent to Forest Service Property, were remonumented. Corners found, restored, or reestablished by Markham in 1952, were also remonumented.

CS 1/16th, set by single proportionate measurement between the S $\frac{1}{4}$ corner and the Center $\frac{1}{4}$ corner.

SW 1/16th, set by intersection of east-west and north-south center lines of quarter section.

NW 1/16th, set by intersection of east-west and north-south center lines of quarter section.

A closed traverse was run from a point near the CS 1/16th corner Section 21, west to the approximate SW 1/16th corner, north to the CW 1/16th corner, west to the W $\frac{1}{4}$ corner, south to the SW Section corner, then northeasterly to the point of beginning. A closed traverse was run from the CN 1/16th Section 21, to the N 1/16th between 20, 21, north to the NW Section corner, east to the N $\frac{1}{4}$ corners, then south to the point of beginning. Limit of closure did not exceed that as defined in Class D, Section 234 of the Manual of Surveying Instruction, 1947.

Feet

Found a 1 $\frac{1}{2}$ " x 4' iron pipe for the $\frac{1}{4}$ corner to Sections 21 and 28

from which

A spruce 80 inches in diameter bears N 74 E, 34.7 feet

A hemlock stump 26 inches in diameter bears S 17 E 57.7 feet

At the corner point set in the ground an iron post 2" x 30" with brass cap marked

T 5 S R 10 W

$\frac{1}{4}$

$\frac{21}{28}$

1968

ORLS 650

from which a new bearing tree:

An alder 8 inches in diameter bears S 73 $\frac{3}{4}$ E 6.0 feet
Scribed $\frac{1}{4}$ S 28 BT 650

Deposited iron pipe alongside iron post.

North on transit random line describing true line which bears N 0-40-14 W

530.0

Approximate location, branch 6 feet wide course N 40 E

