

Feet

1359.0 Point for the SW 1/16th, set in the ground a 2" x 30" iron post with brass cap marked

T 5 S R 10 W

SW 1/16

1968

ORLS 650

from which

A hemlock 16 inches in diameter bears N 3 3/4 W 6.3 feet

A hemlock 33 inches in diameter bears S 33 1/2 E 6.6 feet

From this corner ran north along random transit line describing true line which bears N 0-04-44 W

1301.8 CW 1/16th, as set by Carlich, found a 4" x 4" x 48" wooden post for corner from which

A spruce snag 26 inches in diameter bears N 31 1/2 E 34.9 feet (Top missing)

A hemlock windfall 20 inches in diameter S 23 1/2 W 13.8 feet (Record bearing)


At the corner point set in the ground a 2" x 30" iron post with brass cap marked

T 5 S R 10 W

CW 1/16

1968

ORLS 650



from which new bearing trees:

A hemlock 33 inches in diameter bears S 71 1/2 E 38.0 feet
scribed CW 1/16 S 21 BT 650

A hemlock 26 inches in diameter bears N 47 1/2 E 46.0 feet
scribed CW 1/16 S 21 BT 650

Deposited wooden post alongside iron post

From the above described corner running west along random transit line describing true line which bears N 88-33-14 W

223.0 Branch, course north

1342.5 The 1/4 corner between 20, 21 as reestablished by Markham in 1952, and remonumented by Carlich in 1956. Found 1 1/2" x 48" iron pipe for the corner with rotted 3" x 3" scribed wooden post alongside, from which