

County Surveyor's Record, Tillamook County, Oregon

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

(Reference FSH 5681.65)

History of original corner establishment:

This corner was established in 1882 by the General Land Office (William P. Wright, surveyor). It was remonumented with a brass cap by the Cadastral Engineers.

DIAGRAM

T5S, R10W, W.M.

21	22
28	27

Description of corner evidence found:

Found a 2 inch iron pipe with brass cap marked and a 1 inch alloy pipe

T5S R10W

From which

21	22
28	27

A spruce snag, 37 inches in diameter bears N81E, 22.3 feet distance

A spruce snag, 16 inches in diameter bears S32E, 26.6 feet distance

A hemlock broken stump bears S7W, 24.9 feet distance

A spruce snag 39 inches in diameter bears S89W, 7.1 feet distance


A spruce snag, 24 inches in diameter bears N48W, 19.0 feet distance

Bearing tree signs were on all BT's facing the monument.

Description of monument and accessories I established to perpetuate the original location of this corner

This corner was adequately monumented. Nothing further was done.

Office of County Surveyor County of Tillamook
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 1st day of July, 1968, at 2 o'clock p.m., (signed)
[Signature] by [Signature]
(COUNTY OFFICIAL) (DEPUTY)



BOOK 3