

County Surveyor's Record, Tillamook County, Oregon

CHAINS

10 11

15 14

6S R10W

EVALUATION AND RESTORATION OF LAND SECTION CORNERS

Section Corner Common to Sections 10-11-14-15, W.M.,
Tillamook County, Oregon

ORIGINAL: Albert D. Wilson, Deputy Surveyor, 10-25-1890

Set post 4 in. square, 4 ft. long, 24 ins. deep for corner to Sec. 10-11-14-15, mkd.

T6SR10WS-10 on NW,

T6SR10WS-11 on NE,

T6SR10WS-14 on SE,

T6SR10WS-15 on SW faces with 4 notches on the South, and 2 on the East edges from which

An Alder, 16 in. diam, bears W., 10 lks. dist. mkd.

T6SR10WS-10 & 15 BT

An Alder, 20 in. diam. bears N84°W, 10 lks. dist. mkd.

T6SR10WS-10BT

An Alder, 10 in. diam, bears N27°E, 33 lks. dist. mkd.

T6SR10WS-11BT

No other tree within limits, so I dug a pit 18" x 18" x 12", N45°W, 10 lks. distance. Soil 2nd rate, land rough and broken. Timber is young fir, hemlock, and spruce. Dense undergroth of whortleberry, salmon, and vine maple.

FOUND: 1" galv. pipe 40" above the ground, Original Alder, west, 10 links and an Alder, N84°W, 10 links fallen upon the ground and badly deteriorated. Both had grown from the same stump. Found illegible scribe mark on a piece of alder bark upon the ground. Written testimony in RS Files by H. Lilligren, forester, 1-29-47, states that at that time he saw all scribe marks on the then standing West and Northwest Alders. He, also, states a large boulder in the creek forming a 6 ft. waterfall lies about 30 links to the Northeast.

I found the above as stated.

RESTORED:

I set a 1" galv. pipe 40" above the ground 5 links West of a small brook (as of orig. Notes) and about 10 links East of the West Alder stump.

I mark 4 new BTs:

28" Fir, S77°30'W, 26 feet horizontal dist. mkd.

T6SR10WS14BT

66" Spruce, N66°E, 49 ft. slope dist. mkd.

T6SR10WS11BT

30" Hemlock, N7°W, 51½ ft. slope dist. mkd.

T6SR10WS10BT

8" Hemlock, S34°W, 54.8 ft. horiz. dist. mkd. XBT.

RESTORED BY:

Leonard Whitmore, Till. Co. Dep. Surveyor

WITNESSED BY:

Glenn Horner

DATED: 6-1-67

County Surveyor's Record, Tillamook County, Oregon

RECOVERY	
PROPERTY CORNER INVESTIGATION	
<p>LOCATION</p>	<p>T. <u>6S</u> R. <u>10W</u> Mer. <u>Will.</u> State <u>ORE</u> Forest <u>SIUS.</u> Dist. <u>HCB</u></p> <p style="text-align: center;">LEGEND</p> <p><input type="radio"/> Corner searched-no evidence <input checked="" type="radio"/> Corner or accessory found <input checked="" type="radio"/> Corner marked by perm. mon.</p>
<p style="text-align: center;">DESCRIPTION OF FOUND CORNER</p> <p>MATERIAL: <u>GALV. PIPE</u> SIZE: <u>1"</u> HEIGHT ABOVE GROUND: <u>40"</u> CONDITION: _____ MARKINGS: _____</p>	
<p style="text-align: center;">DESCRIPTION OF FOUND ACCESSORIES</p> <p><u>FOUND ORIG. ALDER, WEST, 10 LKS. AND AN ALDER, N84°W, 10 LKS. FALLEN UP THE GROUND. BOTH HAD GROWN FROM THE SAME STUMP. FOUND ILLEGIBLE SCRIBE MARK ON A PIECE OF ALDER BARK ON GROUND.</u> <small>BADLY DETRIORATED.</small> NOTE: Indicate full investigative details on back of form.</p>	
<p style="text-align: center;">PHOTO IDENTIFICATION</p> <p>Symbol & date _____ Line or Roll _____ Exposure _____ How identified _____ Where filed _____</p>	
<p>BOOK <u>8</u></p> <p>DATE: <u>6-1-67</u></p>	<p>RECOVERED BY: <u>L. WHITMORE</u> TITLE: <u>FORESTRY TECH</u></p>

WRITTEN TESTIMONY IN OUR FILES

BY H. LILLIGREN, FORESTER, 1-29-47, STATES THAT AT THAT TIME HE SAW ALL SCRIBE MARKS ON THE THEN STANDING WEST AND NW ALDERS. HE ALSO STATES A LARGE BOULDER IN THE CREEK FORMING A 6 FOOT WATERFALL LIES ABOUT 30 LKS. TO THE N.E.

I FOUND THE ABOVE AS STATED. I SET A PIPE 5 LKS. ^{WEST AS OF NOTES.} FROM THE EDGE OF A SMALL BROOK AND ABOUT 10 LKS. EAST OF THE WEST ALDER STUMP. I MARK 4 NEW BT'S:

28" FIR, S. 77° 30' E, 26 FT. HORIZONTAL DIST.
 MKD. T6SR10WS14 BT

66" SPRUCE, N. 66° E, 47 FT. SLOPE DIST.
 MKD. T6SR10WS11 BT.

30" HEM., N. 7° W, 51 1/2 FT. SLOPE DIST.
 MKD. T6SR10WS10 BT.

8" HEM., S. 34° W, 54 1/2 FT. HORIZ. DIST.
 MKD. X BT.

Leonard Whitmore