

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

One quarter corner for Section 36 (South side) T4N,
R10W, W.M., Clatsop County, Oregon.

ORIGINAL

Post (Now missing)

16" Hemlock bears N85W 56.5 lks.; now 24" stump,
scribe visible on badly rotted lower face.

8" Hemlock bears S16W 27.5 lks.; now 15" badly rotted
stump, scribe T remaining on lower face.

RESTORED

Var. $21\frac{1}{2}^{\circ}$ E

Set $1\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked
"OREGON STATE BOARD OF FORESTRY $\frac{1}{4}$ S36 1969 RS 707", 32
inches in ground, and from which a:

8" Hemlock bears N56E 19.8 ft.; scribed $\frac{1}{4}$ S36 BT.
8" Hemlock bears N23W 9.5 ft.; scribed $\frac{1}{4}$ S36 BT RS 707.
Old Railroad grade bears E 38 ft., course S45 $^{\circ}$ E by N45W.


Set 5" x 5" x 50" white painted Cedar post 1.0 ft. NW of
corner pipe. Oregon State Forestry Department metal loca-
tion poster on 8" NW BT.

Dated March 31, 1969.

Restored by



Harold J. Russell



Present and witnessed by Stanley Gann

DUPLICATE RECORDING
CLATSOP COUNTY
CS BT-408