

TOWNSHIP 5 SOUTH, RANGE 10 WEST

1/4 Corner, between Sections 27, T5S, R10W  
34

Found iron pipe by iron pipe with brass cap for corner.

From which I found:

How big? →

Big Spruce BT with tag bears N 41° W 51 feet

See Book 1  
Page 400

Corner is marked with pile of stones.  
Corner lies in a swale, draining N-NE.

July, 1969

Found by: Stan Benson, LFCo.

C 1/4 Corner, Section 27, T5S, R10W

Found 1" stainless steel tubing for corner.

From which I found the following BT's:

30" D. Fir bears N 03° E 15.1 feet

1 1/2" Hemlock bears S 74° W 15.7 feet

NO COUNTY RECORD FOR THIS CORNER 11/69

Corner is near top of ridge that descends to the north.

July, 1969

Found by: Stan Benson, LFCo.

CW 1/16 Corner, Section 27, T5S, R10W

Found 1" stainless steel tubing for corner.

From which I found the following BT's:

30" Spruce bears S 13° W 8.5 feet

16" Hemlock bears N 23 1/2° W 17.9 feet

NO COUNTY RECORD FOR THIS CORNER 11/69

Corner lies one chain south of the bottom of a swale which runs to the W-NW.

Corner sets 150' NW of saddle in ridge.  
There is a stone by the corner pipe.

July, 1969

Found by: Stan Benson, LFCo.

W 1/16 Corner, Sections 27, T5S, R10W  
34

Found 1" stainless steel tubing for corner.

From which I found the following BT's:

22" Spruce bears N 03° E 49.7 feet

66" Spruce bears S 66° W 55.7 feet

NO COUNTY RECORD FOR THIS CORNER 11/69

Corner lies approximately one chain NW of a creek on the south end of a small knob.

July, 1969

Found by: Stan Benson, LFCo.