

CORNER RECORD (SEARCH)

Tract or Survey No.

E-13

Index File No.

(Ref. FSM 7151.4)

T. 55 S

R. 10 W

R.D. Hebo


County TILLA

Merid. WILL

N.F. SLUSLAN

State ORE.

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND (CLC 1882 SET POST (1) MKD,
 18" FIR, N. 62° E, 4 FT.
 4" FIR, S. 45° W, 2 1/2 IN.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
 FOUND A STEEL DRIVE SHAFT BAR IN GROUND ALONGSIDE
 OLD ORIGINAL POST
 FOUND 4" FIR SNAG, S. 45° W, 19 1/2 FT. WITH MARKS ROTTED
 OFF.
 THE NE BT IS MISSING.

PHOTO IDENTIFICATION DATA

Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____
 Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PLANE COORDINATE POSITION DATA

State _____ Zone _____
 X _____
 Y _____
 Estab. By _____
 Agency _____

Signature: M. Whitmore Title: Forestry Tech Division: Timber Headquarters: Hebo Date: 5-13-70 7100-52 (3/68)

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

M. WHITMORE, USFS, 1954 RE-WITNESSED 3 TREES;
 18" FIR, N. 62° E, 4 FT. WITH HEALED WITNESS FACE.
 16" FIR, S. 30° 30' E, 34 FT. WITH HEALED WITNESS FACE.
 16" SPRUCE, S. 14° W, 16 1/2 FT. WITH HEALED WITNESS FACE.

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____
 Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

REMARKS

CLARENCE DUNN, LOCAL LANDOWNER, NOW 83 YEARS OLD AND LIVING ON THIS LAND ALL HIS LIFE STATES THIS OLD ROTTED POST WAS THE ORIG. HE SAW SCRIBE MARKS ON IT DURING HIS BOYHOOD. IN FACT HIS FATHER WAS EMPLOYED BY THE G-L-C SURVEYOR 1882 TO HELP MONUMENT THIS CORNER AS WELL AS OTHERS IN THE TOWNSHIP.

Index File No. T. 55 S R. 10 W M. WILL Tract or Surv. No. Sec. Cor 3-4-7-103