


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established in January of 1872 by
J. W. Meldrum

20" fir brs. N56E 397 lks

40" fir brs. S45W 290 lks



Description of corner evidence found:

Found remains of original post in poor condition.
Found 4x5x14" of post below surface with a steel shaft
bar in ground alongside corner. from which

40" snag brs. S45W 191.4 ft (orig) - with mark rotted off

15" spruce brs. S14W 16.5 ft
with healed face

18" fir brs. N62E 4.0 ft
with healed face


15" fir brs. S38½E 34.0 ft
with healed face

} Established in 1954
All have tags

Description of monument and accessories established to perpetuate the
original location of this corner

Set 2"x30" iron pipe with brass cap mkd

T5S R10W



1970
650

Buried 4x4x14" post alongside corner
Put shaft alongside corner

Set a fence post with sign ± 5 ft south facing west

Office of County Surveyor County of TILLAMOOK
State of OREGON, I hereby certify that the within instrument was filed in this office
for record on the 1st day of July, 1970, at o'clock m., (signed)
[Signature] by
(COUNTY OFFICIAL) (DEPUTY)

REGISTERED
OREGON
LAND SURVEYOR

[Signature]
JULY 10, 1964
TOM O. McCULLOUGH
650