


CERTIFIED RECORD OF LAND CORNER MONUMENT.

History of original corner establishment:

Corner established in 1896 by Tillamook County Surveyor



Description of corner evidence found:

No monument found

Found 27" fir brs. N85W 8.6 ft.  
Has been chopped out & C.S. visible - with tag

46" fir brs. S42E 8.0 ft.  
with tag - evidence of face

Description of monument and accessories established to perpetuate the original location of this corner

Set 2"x30" iron pipe with brass cap mkd

T5S R10W  
Sec. 4  
CE1/16  
1970  
650

Set 2 fence posts with signs  $\pm$  5 ft east facing south  
 $\pm$  5 ft south facing east

Office of County Surveyor County of Tillamook  
State of OREGON, I hereby certify that the within instrument was filed in this office  
for record on the 15<sup>th</sup> day of May, 1970, at        o'clock        m., (signed)  
[Signature] (COUNTY OFFICIAL) by        (DEPUTY)

REGISTERED  
OREGON  
LAND SURVEYOR

[Signature]  
JULY 10, 1964  
TOM O. McCULLOUGH  
650