


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established in 1878 by Henry Meldrum



Description of corner evidence found:

Found 8x6 post set by M. Whitmore in 1958 from which

40" fir snag brs. N53E 17.2 ft (orig)
scribing visible

44" fir snag brs. S73W 78.0 ft (orig)
scribing visible

34" spruce brs. S87 $\frac{1}{2}$ W 66.0 ft
face healed over - with tag

28" fir brs. N4E 100.0 ft
face healed over - with tag

Description of monument and accessories established to perpetuate the original location of this corner

Set 2"x30" iron pipe with brass cap mkd

T4S, R10W

$\frac{17}{20}$

1970

650 from which

18" alder brs. N75W 19.8 ft
bark scribed T4S R10W S17 BT

Set post alongside corner

Set fence post with sign + 5 ft west facing south

Office of TILLAMOOK County of SURVEYOR
 State of OREGON, I hereby certify that the within instrument was filed in this office
 for record on the 13th day of May, 1970, at o'clock m., (signed)
[Signature] (COUNTY OFFICIAL) by (DEPUTY)

REGISTERED
OREGON
LAND SURVEYOR

Tano. McCullough
JULY 10, 1964
TOM. O. McCULLOUGH
650

BOOK 3

363

Form R6-7100-57 (9/66)

Book 3

5/8/70