

CHAINS

T3S R10W
EVALUATION AND RESTORATION OF LAND SECTION CORNERS

E 1/16 corner common to Secs 7-18 W.M., Tillamook County, Oregon

Original monument: Pipe

Found 1" pipe 3" above ground.

Found 18" dead pine, S.75°W., 24 Ft. with visible mks S 1/16 BT(orig)

Found a location tin by William Anderson, Tillamook County surveyor who subdivided this area and set this corner 2-26-51. *see BK 1 P 94*

I cannot find another bearing tree.

This corner is located about 300 feet west of an open sand-field.

I mark New BT^s.

10" fir, S.18°E., 28½ ft. mkd E 1/16S18 BT

18" pine, N.10°30' W., 36 ft. mkd E 1/16S7 BT

By Leonard Whitmore, Tillamook County Dep. Surveyor. 9-20-65

Witnessed by: Vernon Scheese

T3S, R10W, CW 1/16 for Section 18 W.M., Tillamook County, Oregon

Original monument: Post

Found 5" wood post in poor condition 18" above ground mkd 1/16S on East side.

Found 12" dead pine, S.4°W., 7 ft. mkd CS 1/16 BT.

Found 16" fir, N.74°W., 14½ ft. mkd S 1/ visible in partially healed face.

This corner is located on a gentle west slope. William Anderson, Tillamook County surveyor set this corner by transit and chain subdivision 2/12/51. *see Book 1 Page 95*

I mark New BT

14" fir, S. 66W., 7.4 ft. mkd CW 1/16 BT.

By Leonard Whitmore, Tillamook County Dep. Surveyor. 9-21-65

Witnessed by: Bill Linn

County Surveyor's Record, Tillamook County, Oregon

CHAINS

T3S, R10W 1/4 corner common to Sections 6-7 W.M., Tillamook County, Oregon

Found 3" x 3" wooden post 6 Ft. above ground. (Not original)

Found rotted Hem. stump, S. 73° E., 29 Lks. with a visible mark .4 (orig) The N. E. orig. spruce BT is fallen upon the ground.

T3S, R10W 1/4 corner common to Sections 7-18 W.M., Tillamook County, Oregon

Found 18" stub 4' high in poor condition with orig. marks 4S for 1/4 corner. The Tillamook County surveyor marked additionally 1/4S on West Side. 2-26-51

Found 26" Hem., N. 76° W., 4.6 Ft. with visible marks S¹. (orig).
Found 24" Hem., N. 13° W., (not N. 13° E as in orig. notes).
8.4 Ft. with rotted out hole at witness Blaze.
William Anderson Tilla. Co. surveyor marked

Additionally C.S. 1/4 on the N. W. BT. 2-26-51

Witness: Bill Linn, USFS

T3S, R10W., E 1/16 corner common to Sections 7-18 W. M., Tillamook County, Oregon

Found 1" pipe 3" above ground.

Found 18" dead pine, S. 75° W., 24 Ft. with visible marks S 1/16 BT. (orig). Found a location tin by William Anderson Tillamook County surveyor who subdivided this area and set this corner 2-26-51

I cannot find another bearing tree.
This corner is located about 300 feet west of an open sand-field.

Original Monument.

New BT^s

10" fir, S. 18° E., 28½ ft. marked E 1/16S18BT.
18" pine, N. 10° 30' W., 36 Ft. marked E 1/16 S7BT.

Witness: Vernon Scheese, USFS.

T3S, R10W, CW 1/16 for Section 18 W.M., Tillamook County, Oregon

Found 5" wood post in poor condition 18" above ground marked 1/16S on East side. (orig)

Found 12" dead (orig) pine, S. 4° W., 7 Ft. marked CS 1/16 BT.
Found 16" fir, N. 74° W., 14½ Ft. marked S 1/ visible in partially healed face. (orig)

This corner is located on a gentle west slope. William Anderson, Till. Co. surveyor set this corner by transit and chain subdivision 2-12-51

Original Monument.

New BT

14" fir, S. 66° W., 7.4 Ft. marked CW 1/16BT.

Witness: Bill Linn, USFS

see page 19

see page 19

BOOK 3

12A