

CHAINS

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

East one sixteenth corner (common to) Sections 16 and 21,
T1N, R10W, W.M., Tillamook County, Oregon.

ORIGINAL

3/4" iron pipe by Schrader 1918 (found in place, rusted)
from which:

Line blazes bear east and west.

RESTORED

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked
"OREGON STATE BOARD OF FORESTRY E 1/16 S16 S21 1965 RS 401",
30 inches in ground, and from which a:

36" Hemlock bears S69°E 24.4 ft.; scribed E 1/16 S21 BT.

27" Hemlock bears N79 1/4°W 31.8 ft.; scribed E 1/16 S16 BT RS 401.

Set 4" x 4" x 60" white painted Cedar post 1.0 ft. NE of
corner (pipe).

Oregon State Forestry Department metal location poster on
36" Hemlock BT.

Dated November 18, 1965.

Restored by Allan E. Duncan under my direction.
Allan E. Duncan, Forestry Aide

REGISTERED
OREGON
LAND SURVEYOR

Richard A. Morris

MAY 10, 1957
Richard A. Morris
401

Present and witnessed by C. Curl
L. Thompson

BOOK 3

★