

County Surveyor's Record, Tillamook County, Oregon

CHAINS

Page 7 T.3S.R.10W. (cont.) 4.S.10.

I set 1" pipe 24" above ground and mark a 31" hem. S. 18° W.
128 1ks. Mkd. T3.S.R.10.W., S.35BT.

Leonard Whitmore, Tillamook County dep. surveyor 5-9-62

Witness: Ed Gary

T.3-4S.R.10W.

~~35 36 T3S~~
~~2 1 T4S~~

Evaluation and Restoration of Land
Section Corners

Sec. Cor. to secs. 35-36-1-2

Original Monument:

5" x 5" post

Original Witnesses:

30" fir, S. 12° E., 63 1ks. Mkd. T4S.R.10W., S.1 BT.
50" fir, S.50°W., 53 1ks. Mkd. T4S.R.10W., S.2 BT.
30" fir, N.53°W., 120 1ks. Mkd. T3S.R.10W., S.35 BT.
24" fir, N. 33°E., 163 1ks. Mkd. T3S.R.10W., S.36 BT.

I found a 2" x 2" squared fir post 48" above ground in good
condition set by M. Whitmore 2-28-51.

I found the orig. 50" snag, N.29°E., (not N.33°E. as in orig.
record) 53 1ks. with the lower half of a "B" visible.

The S.W. and S.E., and N.W. BT^S are in their proper bearings
and distances but all marks are rotted away.

I set 1" pipe 2 ft. above ground and mark 4 new BT^S.

11" fir, S.50°W., 46½ ft. Mkd. T4S.R.10W., S.2 BT.
20" fir, N. 21° 30'W., 29 ft. Mkd. T3S.R.10W., S.35 BT.
32" fir, N. 59°E., 19 ft. Mkd. T3S.R.10W., S.36 BT.
9" cedar, S. 27°E., 36½ ft. Mkd. T4S.R.10W., S.1 BT.

Leonard Whitmore, Tillamook County dep. surveyor, 5-11-62
Witnesses: Ed Gary
M. Whitmore

BOOK 3