

CHAINS

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

One quarter corner common to Sections 8 and 17,
Township 1 South, Range 9 West, W. M., Tillamook
County, Oregon.

ORIGINAL

Post (missing) from which a:

64" Spruce bears South 52 lks.; now 48" stump, scribe 1/4 visible.
32" Spruce bears N 12 W 35 lks.; missing.

RESTORED

Var 21 1/2 E

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked
"OREGON STATE BOARD OF FORESTRY 1/4 S8 S17 1967 RS 707",
33 inches in ground and from which a:

6" Hemlock bears S 59 W 63.2 ft. from face; scribed 1/4 S17 BT.
22" Hemlock bears N 76 W 104.8 ft. from face; scribed 1/4 S8
BT RS 707.

Set 4" x 4" x 60" white painted Cedar post 1.0 ft. SE of corner pipe.
Oregon State Forestry Department metal location post on 6" Spruce N
41 1/4 W.

Dated June 9, 1967.

Restored by

REGISTERED
OREGON
LAND SURVEYOR

Harold J. Russell

JULY 9, 1965
HAROLD J. RUSSELL
707

Present and witnessed by C. Curl
B. Harris