


CHAINS



TILLAMOOK COUNTY REWITNESS

SEC. COR. # 27 T. 4 S R. 10 W., WM.

HISTORICAL: Book 4 Page 96 ± 1956


|                  |             |     |
|------------------|-------------|-----|
| Triple Stump     | S 49° E     | 285 |
| 2" IP fence Cor. | S 24° 46' W | 321 |
| 2" IP fence Cor. | N 8° W      | 488 |

| CONDITION   | FOUND:                                   |             |       |
|-------------|--|-------------|-------|
| not useable | 1 1/4" IP + 4" deep in VS # 101 blacktop |             |       |
| * good      | stump remain                             | S 49° E     | ± 285 |
| * good      | 2" IP fence Cor.                         | S 24° 46' W | 3214  |
| * good      | 2" IP fence Cor.                         | N 8° W      | 488   |
| good (USFS) | 4" x 4" x 84 Post                        | ± N 8° W    | ± 48  |

COMMENTS: \* = Tillamook County Corner Tag Placed.

REWITNESS

1 SET NOTHING (See comments)  
 "x" "x" " Post N.W. feet  
 " Hat Section S. E.



NEW ACCESSORY:

|                                     |         |        |
|-------------------------------------|---------|--------|
| X in top RR iron @                  | S 76° E | 29.93  |
| S gate post of school               |         |        |
| Top Fire hydrant in front of school | N 55° E | 156.89 |

COMMENTS: No hat section or post erected as USFS already has 4" x 4" x 84" section line crossing post erected.

IN THE PRESENCE OF: ALICIA E. DUNCAN

BOOK

DATE: 8/67

PHOTO#:

John L. Carlisle

Count Surveyor

\* = County corner tag affixed.