

CHAINS

RESTORED CORNER FOR STATE OF OREGON—DEPARTMENT OF FORESTRY

Section corner common to Sections 3, 4, 9 and 10,  
Township 6 South, Range 9 West, Willamette Merid-  
ian, Tillamook County, Oregon.

ORIGINAL (By Wygant in 1908 Retracement).

Post (missing, 36" Cedar log covering point for corner) from which:

- 12" Hemlock bears N 4 E 20 lks.; now 26" Snag, scribes marks visible on badly rotted face.
- 12" Hemlock bears S 37 E 34 lks.; now 16" stub, scribe BT exposed on lower face, upper face rotted away.
- 12" Hemlock bears S 23° 40' W 32 lks.; now missing, roots in place.
- 12" Hemlock bears N 31 W 31 lks.; now 26", scribes S4 BT visible on mostly grown over face.

RESTORED

Var 21½E


Set 12 penny nail in the 36" Cedar log in middle of an X, from which a:

- 30" Hemlock bears N 5½ W 18.7 ft.; scribed T6S R9W S4 BT RS 707.
- 10" Hemlock bears S 63 E 13.6 ft.; scribed T6S R9W S10 BT.
- 40" Hemlock bears N 35 E 50.8 ft.; scribed T6S R9W S3 BT.
- 26" Hemlock (original) bears N 31 W 20.5 ft.; scribed BT.


Set 4" x 4" x 60" white painted Cedar post 2.0 ft. West of corner Point. Oregon State Forestry Department metal location poster on 30" Hemlock BT.

Dated June 25, 1968.

Restored by



*Harold J. Russell*



Present and witnessed by K. Cameron