

County Surveyor's Record, Tillamook County, Oregon

CHAINS	
29	4S R9W
32	<p style="text-align: center;">EVALUATION AND RESTORATION OF LAND SECTION CORNERS</p> <p style="text-align: right;">One-quarter corner common to sections 29-32, W.M., Tillamook County, Oregon</p> <p>ORIGINAL: Henry Meldrum, September 3, 1878</p> <p style="padding-left: 40px;">Set a post (fir), 4½ feet long, 4 inches diameter, for ¼ section corner, from which</p> <p style="padding-left: 40px;">A fir, 30" diameter, bears North 67° West, 20 lks. distance,</p> <p style="padding-left: 40px;">A fir, 40" diameter, bears South 60° East, 43 lks. distance.</p> <p>FOUND:</p> <p style="padding-left: 40px;">30" snag, North 67° West, 20 links (as Orig.) with mks. rotted off,</p> <p style="padding-left: 40px;">40" snag, South 60° East 43 links (as orig.) with mks. burnt off,</p> <p style="padding-left: 40px;">From this point to the West 243 feet is an original line blaze on a slab that had fallen off a snag.</p> <p style="padding-left: 40px;">To the East 136 feet is an original blaze on a pitch slab of a snag, also, an original line blaze on a snag approximately ¼ mile to the east. The corner point is ½ mile east of the N-S Section Line. With this evidence I set corner.</p> <p>RESTORED:</p> <p style="padding-left: 40px;">I set 1" pipe 30" above the ground. A ridgetop running E-W is 40 feet to the South.</p> <p style="padding-left: 40px;">I mark 2 new BTs:</p> <p style="padding-left: 40px;">16" Alder, South 23°30'E., 33½ feet mks. ¼S32BT</p> <p style="padding-left: 40px;">12" Spruce, North 2° E., 9 feet mkd. ¼S29BT</p> <p>RESTORED BY:</p> <p style="padding-left: 80px;">Leonard Whitmore, Tillamook County Deputy Surveyor</p> <p>WITNESSED BY:</p> <p style="padding-left: 40px;">Wendel Jones M. Whitmore</p> <p>DATED: 3-28-67</p>


Bk. 3

County Surveyor's Record, Tillamook County, Oregon

CHAINS

Index File No. _____ CORNER RECORD (SEARCH) Tract or Survey No. _____ No. V
 T 4S R. 9W R.D. HeBo County TILLAMOOK
 Merid. Will. N.F. SUUSLAW State ORE.

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND THE ORIG. POST IS GONE.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

FOUND 30" SNAG, N. 67° W., 20 LKS. (AS ORIG.) WITH MKS. ROTTED OFF.
 FOUND 40" SNAG, S. 60° E., 43 LKS. (AS ORIG.) WITH MKS. BURNT OFF.

PHOTO IDENTIFICATION DATA

Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____
 Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR BY FEATURES, ALSO HOW TO REACH CORNER

FROM THIS POINT TO THE WEST 243 FT. IS A ORIG. LINE BLAZE ON A SLAB THAT HAD FALLEN OFF A SNAG.
 TO THE EAST 136 FT. IS A ORIG. BLAZE ON A PITCH SLAB OF A SNAG, ALSO A ORIG. LINE BLAZE ON A SNAG APPROX 1/4 MILE TO THE EAST. THE COR. POINT IS 1/2 MI. E. OF THE N-S SEC. LINE. WITH THIS EVIDENCE I SET COR.

PLANE COORDINATE POSITION DATA

State _____ Zone _____
 X _____
 Y _____
 Estab. By BOOK 3
 Agency _____

Signature _____ Title _____ Division _____ Headquarters _____ Date 8- 5680-2

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

I SET 1" PIPE 30" ABOVE GROUND.
 A RIDGETOP RUNNING E-W IS 40 FT. TO THE SOUTH.

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

I MARK 2 NEW BT'S:
 16" ALDER, S. 23° 30' E., 33 1/2 FT. MKD. 1/4 S 32 BT. Leonard Whitmore, Forestry Tech.
 12" SPRUCE, N. 2° E., 9 FT. MKD. 1/4 S 29 BT. WENDEL JONES
M. WHITMORE } WITNESSES

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

REMARKS

BOOK 3

Index File No. T. R. M. Tract or Surv. No. Cor. _____

GPO 892-946

BOOK 3

270
 Bk # 3