

County Surveyor's Record, Tillamook County Oregon

T3S, R8W, Sec. Cor.	18	17	RESTORED	Oct. 13, 1969.
	19	20	by W. A. MARKHAM	

CHAINS

When this corner was set by the Government survey in 1882, 4" maples were used for bearing trees, and they have disappeared.

However, the record has very definite topography ties:

Running NORTH, between Sections 19 and 20, at North 70.00 ch, or 10 ch south of the corner, ENTER BOTTOM.

Running NORTH from the corner, between Sections 18 and 17, over bottom, at North 3.00 ch, BROOK, cs. SE; 3 lk wide.

Running to the corner from the west, between Sections 18 and 19, at 65.00, or 2.90 ch west from the corner, ENTER BOTTOM.

Running to the corner from the East, between Sections 17 and 20, at west 76.00, or 4.18 ch east of the corner, a CREEK, 25 lks wide (Moon Creek); at 79.70, or 48 links, or 32 feet east of the corner, ASCEND BANK.

In 1903, this corner was Re witnessed by the County Surveyor. (See Re Witness book \_\_\_\_\_ page \_\_\_\_\_)

From the existing stake which was taken to be the corner, new witness trees were made:

- FIR, 22", S10\*E, .52 ch.
- ALDER, 12", S73\*E, .55 ch.
- " 10" S60\* E .64 ch.
- " 10" N 72<sup>1</sup>/<sub>2</sub>\*E, .55 ch.

I find what I take to be the NE Alder witness tree. It is a stump of what would have been a 10" Alder, with a very old, rotted flat bottom of a notch cut into the tree; the notch weakened the tree so that it broke off in the wind, a barber chair break; the tree above the lower part of the cut, which would have carried the face of the blaze, is gone; but taking this Alder stump to be the NE bearing tree, I measure from it S 72<sup>1</sup>/<sub>2</sub>\* W, 55 links, or 36 feet, which point falls in the old fence which is said to be on the Section Line, North and South; and the position fits the topography ties, in all four directions, as listed above, as well as could be asked for. Therefore, I take this to be as correct a restoration of this corner as can be made at this time.

At the point so restored, I drive a steel reinforcing bar, 5/8" by 4 feet, 2<sup>1</sup>/<sub>2</sub> feet in the ground, and mark new Bearing Trees:

- Maple, 6", N 41\* E, 31.7 feet, scribe on bark "S 17 1842 BT"
- Alder, 16" S 61\* E, 75.3 feet, " " "S 20 1842 BT"

From this corner as restored, I run random transit traverse, initial bearing from needle, Decl. 22\* East, to the original Quarter corner 18/17, as restored by State Forestry in 1962. I make this tie to be North 2587.9 feet, and East 115.8 feet, or North 02\*34' East, 2590.4 feet. At North 1284.4, or short of the midpoint by 9.6 feet, and at East 48.6 feet, or West 8.8 feet from the midpoint, I find a very old 2" pipe (Boiler Tube) and remnant of East and West fence, supposed to be the 1/16th corner.



*Book 3*