


CERTIFIED RECORD OF LAND CORNER MONUMENT

History of original corner establishment:

Corner was originally set in November of 1880 by the General Land Office. The Tillamook County Surveyor set two new BT's in 1887, one of which is still in evidence.



Description of corner evidence found:


- 3/4" iron pipe 30" above ground from which
 - A 30" fir stump brs N31E 107.6 ft; (1887); scribing faint; (tagged)
 - A 17" fir brs S79E 15.3 ft; (tagged)
 - A 16" fir brs N50W 11.0 ft; (tagged)

Description of monument and accessories established to perpetuate the original location of this corner

Set a 2" x 30" iron pipe with brass cap mkd T 5 S R 9 W

$\frac{1}{4}$ $\frac{21}{28}$
1969
650

- Deposited 3/4" pipe alongside brass cap
- Set a 6' steel post north of the corner with F.S. boundary sign facing west
- Set a 6' steel post east of corner with a F.S. boundary sign facing north.
- Painted red band around each BT



Office of County of

State of, I hereby certify that the within instrument was filed in this office for record on the day of; 19....., at o'clockm., (signed)

..... by (DEPUTY)

(COUNTY OFFICIAL)