


CERTIFIED RECORD OF LAND CORNER MONUMENTA

History of original corner establishment:

Corner was originally set in November of 1880. He set a stone and built a stone mound, but scribed no BT's. In 1887 W.W. Hayes, the Tillamook County Surveyor set appost and marked 4 BT snags.



Description of corner evidence found:

A 3/4" pipe 30" above ground. An old wooden post 12" long in rock mound with scribing visible from which

A 14" fir brs N41½E 10.5 ft; scribing visible

A 15" alder brs S42½E 19.0 ft; bark scribed

A 15" alder brs S29W 35.5 ft. bark scribed

A 20" fir brs N31W 9.0 ft. scribing visible

1887 Bt's in their proper location, but scribing rotted off.

Description of monument and accessories established to perpetuate the original location of this corner

Set 2" x 30" iron pipe with brass cap mkd T 5S R 9 W

Set 3/4" pipe and old post beside corner and piled stones around pipe
20 | 21
29 | 28
1969
650

Set a 6' steel post north of corner with F.S. Boundary sign facing east

Set a 6' steel post west of corner with F.S. boundary sign facing south

Placed BT tags on all BT's. Painted red band on all BT's.

REGISTERED
OREGON
LAND SURVEYOR

Tom O. McCullough

JULY 10, 1964
TOM O. McCULLOUGH
650

Office of..... County of.....
State of....., I hereby certify that the within instrument was filed in this office
for record on the day of.....; 19....., at..... o'clockm., (signed)
..... by
(COUNTY OFFICIAL) (DEPUTY)

BOOK 3

815

Rk 3

BR-72