


CERTIFIED RECORD OF LAND CORNER MONUMENTAT

History of original corner establishment:

Corner established July 24, 1898.
Corner re-established by Caudle in 1880 while re-tracing original 1879 line by Henry Meldrum.
Set stone 18 x 8 x 6 for corner to sec. 35 & 36, September 1, 1880.



Description of corner evidence found:

Found stone with X carved on top, 4 notches on west face and 3 notches on north face.

Found 4x4 cedar with scribing by Whitmore. from which


12" spruce brs. N82E 54.8 ft.
scribed T3S R9W S36 BT (Whitmore's)

34" spruce brs. N47W 25.2 ft.
scribed T3S R9W S35 BT

Found what could have been original alder BT S10E 10.0 ft. as did Whitmore, but this is questionable.

Description of monument and accessories I established to perpetuate the original location of this corner

In position of corner I set a 2 1/2" x 30" iron post with brass cap mkd:



Placed original stone and cedar post alongside brass cap.

Set 6' steel post with boundary signs facing west.

February 2, 1970

REGISTERED
OREGON
LAND SURVEYOR

Tom O. McCullough
JULY 10, 1964
TOM O. McCULLOUGH
650

Office of *County Surveyor* County of *Tillamook*
State of *OR*, I hereby certify that the within instrument was filed in this office
for record on the *2* day of *February*, 1970, at *12* o'clock *noon*, (signed)
J. L. Caudle by *Tom O. McCullough*
(COUNTY OFFICIAL) (DEPUTY)